

ANC25LA049

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Image of damage to right wing (Courtesy of Airport Manager)