

ANC25LA050

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Image of airplane after gear up landing (Courtesy of airport operations)



Photograph 2 - Image of damage to belly of airplane (Courtesy of operator)