

ANC25LA057

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of airplane where it came to rest (Courtesy of FAA)



Photograph 2 - View of damage to the floats (Courtesy of FAA)



Photograph 3 - View of the wing underwater (Courtesy of FAA)