

ANC25LA059

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Image of wings, fuselage, and empennage (Courtesy of Owner)



Photograph 2 - Main landing gear spring to fuselage attach point (Courtesy of Owner)



Photograph 3 - Fractured main landing gear spring attached to wheel axle (Courtesy of Owner)