

ANC25LA068

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Image of damage to fuselage (Courtesy of Owner)



Photograph 2 - Image of damage to airplane fuselage (Courtesy of Owner)