

ANC25LA070

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Image of damage to left wing (Courtesy of Owner)



Photograph 2 - Image of damage to right wing tip (Courtesy of Owner)



Photograph 3 - Image of damage to right wing (Courtesy of Owner)