

ANC25LA071

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of bottom of right wing and right side of fuselage (Courtesy of pilot)



Photograph 2 - View of damage to the top of the right wing. (Courtesy of pilot)