

ANC25LA076

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the airplane and damage to left wing. (Courtesy of operator)



Photograph 2 - View of left and right rudder pedals. (Courtesy of FAA)



Photograph 3 - View of the failure of the left rudder assembly (Courtesy of FAA)