

ANC25LA083

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of accident airplane at accident site (Courtesy of the owner)



Photograph 2 - View of landing gear. Bungees still attached, fractures from overload from hard landing.