



Mark Ward
Aviation Accident Investigator
AS-ANC

Date: September 1, 2025

Subject: ANC25LA083 Landing gear inspection

Post examination of the landing gear revealed all fractures in the landing gear were from overload forces from the hard landing. The airplane's main landing gear impacted a gravel berm that was about 3 ft high.