


ANC25LA088

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Image of horizontal stabilizer, wings, and fuselage (Courtesy of Owner)



Photograph 2 - Aerial view of accident airplane (Courtesy of Owner)



Photograph 3 - Image of accident airplane at accident site (Courtesy of Owner)