

ANC25LA101

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front view of the accident airplane and condition of the runway (Courtesy of the pilot)



Photograph 2 - Side view of the accident airplane (Courtesy of the pilot)



Photograph 3 - Aft view of the accident airplane (Courtesy of the pilot)



Photograph 4 - Damage to the vertical stabilizer and rudder (Courtesy of the pilot)