


ANC25LA108

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident airplane at accident site (Courtesy of Owner)



Photograph 2 - Image of fuselage and empennage (Courtesy of Owner)