

ANC25LA110

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left wing of accident airplane (Courtesy of operator)



Photograph 2 - Damage to lower spar cap in the left wing(Courtesy of Operator)