

Carburetor Icing Probability Graph – ANC25LA112

Airplane: Cessna 172

Engine: Continental O-300-A

Fuel: 100LL

Accident Date: 09/21/2025

Accident Location: Yakataga, AK

Accident Time: 1930 AKDT

Weather: Observation Facility (YAK) reported temperature 46° F; dew point 43° F

Observation Facility (CDV) reported temperature 46° F; dew point 37° F

Source: Federal Aviation Administration
Special Airworthiness Information Bulletin CE-09-35
Carburetor Icing Prevention

