

ANC25LA119

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of damage to the right wing (Courtesy of FAA)



Photograph 2 - View of the airplane where it came to rest (Courtesy of FAA)