

N 321BA ✓

Bering Air, Inc. Discrepancy Log

BA 10601

Discrepancy		Status			Corrective Action	
Date:	Hobbs:	Date:	Hobbs:	Landings:	Date:	Hobbs:
4/19/2021 ✓	24.6 ✓				2/5/2021 ✓	24.6 ✓
Landings:	AFTT:	MEL:	Cat:	MX Action:	Landings:	AFTT:
16 ✓	24.6 ✓				16 ✓	24.6 ✓
Throttle Quadrant Friction locked/jammed, knob will not move at all. ✓		MEL Expires:			Removed and replaced engine control quadrant P/N C100465-3 S/W APW21 and tension knob P/N 2662005-8 per Cessna 208B MM 76-10-01.	
		Signature:			[Redacted Signature]	
		Date:	Hobbs:	Landings:	[Redacted Signature]	
		1st Extension Expires:			[Redacted Signature]	
		Signature:			RII [Redacted Signature]	
		Date:	Hobbs:	Landings:	PASS ✓	
		2nd FAA Approval Extension Expires:				
Signature: [Redacted Signature]		Signature:			Signature:	