

ANC26LA025

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Image of accident airplane at accident site (Courtesy of Operator)



Photograph 2 - Image of left wing lift strut (Courtesy of Operator)