



Photo 18. Tail rotor gearbox and broken pitch control tube.