



Photo 2 - Right side of helicopter. Tail rotor drive shaft is bent and some hangers are damaged.