



Photo 5 Rear Aspect of Fire Damage to Right Stub Wing Assembly