



Photo 4 - Mechanical damage to the sensor, caused by the failed magnet. It was mounted oppsite the magnet.