



Photo 4. Collapsed Nosed and Left Main Landing Gears, Buckled Struts and Tree Branches in Left Wing