



Photo 1 – View of wreckage from left front. The wreckage is in a small clearing; the engine, wings, and tail section are easily identified. The cabin area has been mostly consumed by fire.



Photo 2 - A left side view of the wreckage. Much of the cabin has been consumed by fire. A power cable can be seen, in the photograph.



Photo 3 - A powerline is seen, with several cables strung along each pole. One of the poles is broken, near the top, and the cable appears to be pulled down.