



Photo 1. Ice from right fuel strainer bowl (Photo Courtesy of Continental Motors)