




Photo 2. Ice from left fuel strainer bowl (Photo courtesy of Continental Motors)