



Photo 6 - Number 5 cylinder, seized piston, and fractured connecting rod cap