

Folkerts Michael

Subject: FW: CEN14LA374 - N13SK - magneto update

Inspector Shaul
Please see the attached Pictures for the Magneto off of 13SK.

At the start of this week the magneto was removed off of N13SK by my maintenance staff. Once the magneto was placed on the bench, the cover was opened up and it was seen that the points were not opening. The reason the points would not open was because of the screws that hold each point in their operation position had be come loose.

Steve Brown had also told me that he has seen this happen before with this type of mag, but not with both points at the same time.

The Magneto was installed new by Lycoming when the engine was assembled and at a total time of 582 hours.

Please let me know if you need further information or pictures.

Thanks You

Ryan Reeves

