

Lindberg Joshua

From: [REDACTED]
Sent: Friday, September 12, 2014 1:33 PM
To: Lindberg Joshua
Subject: pictures

Hi Josh

I have just sent you about 6 pictures. Perhaps more than you needed but more is better than less. Let me know if you received them. I included the main rotor shot as it clearly shows that the cable was into the rotor system. I am leaving today at 2 CST. I will return Monday at 0730. Are you interested in having Inspectors statements? In the past I have provided them. I can get you those next week.

Jeffrey F. Rock
Principal Inspector (Operations)
ACE-01 Des Moines FSDO
[REDACTED]

Lindberg Joshua

From: [REDACTED]
Sent: Friday, September 12, 2014 1:43 PM
To: Lindberg Joshua
Subject: One more thing

Josh,

The broken wire is a 3/8 inch Extra High Strength steel wire. 7 strand wrap. It is a shield or static wire.

The structures between the broken strand are 1650 feet apart. The lines below are 345,000 KV lines. They were not hot at the time so we don't have an actual cut time but 1209 is real close.

I obtained this information when I interviewed a Mid-American energy structures engineer in charge of this span

Jeffrey F. Rock
Principal Inspector (Operations)
ACE-01 Des Moines FSDO
[REDACTED]