



Photo 1 – Aerial View of Accident Site (Textron)



Photo 2 – Aerial View of Accident Site (Texas DPS)



Photo 3 – View of Main Wreckage



Photo 4 – View of Main Wreckage



Photo 5 – View of Main Wreckage



Photo 6 – View of Engine (CMI)



Photo 7 – View of Propeller Flange (CMI)



Photo 8 – View of Propeller Blades