



Photo 1 – View to the south end of runway 33 and where N623HS began its takeoff roll.



Photo 2 - View to the north and the departure end of runway 34. Note the uphill slope.



Photo 3 - Severed branches at the top of 50-foot trees.



Photo 4 - Severed tree trunk at the crash site. Note also the bark stripped from the trunk.



Photo 5 - Inverted wreckage of N623HS, revealing both wings and engine. Note the smoke haze.



Photo 6 - The inverted Continental O-200-A powerplant.



Photo 7 - Substantive portion of propeller blade A.



Photo 8 - Fragmented blade tip from propeller blade B.