



Photo 1 – View of the airplane at the accident site.



Photo 2 - View of the airplane at the accident site.



Photo 3 - View of the airplane at the accident site.



Photo 4 - View of the airplane's empennage at the accident site.



Photo 5 - View of the airplane at the accident site.



Photo 6 - View of a ground scar at the accident site.



Photo 7 - View of red media in a ground scar at the accident site.



Photo 8 - View of a linear witness mark near a ground scar at the accident site.



Photo 9 - View of a propeller blade.



Photo 10 - View of blue liquid below the left fuel tank's filler neck.



Photo 11 - View of a tube within the pitot system.



Photo 12 - View of the accident engine operating in a test cell.



Photo 13 - View of the repaired carburetor mounted on the accident engine within the test cell.



Photo 14 - View of seat rail supplied by Textron Aviation.