



Photo 1 - Main Wreckage at Accident Site Front View



Photo 2 - Main Wreckage at Accident Site Side View



Photo 3 - Initial Ground Scar Evidence of Impact Angle



Photo 4 - Aerial View of Accident Site Ground Scars




Photo 5 - Track Marks (correlating to the nose and left main landing gear) Prior to Initial Impact Ground Scar



Photo 6 - Recovered Wreckage at Casey Municipal Airport Secure Hangar



Photo 7 - Engine and Propeller Assembly



Photo 8 - Torsional Stress Mark Signatures on the Engine Crankshaft Propeller Flange