

December 1, 2014

Lawrence Tyler Francis

Pilot Certificate: [REDACTED]

N(X)625ZH

The aircraft crashed shortly after takeoff from Las Cruces Intl. Airport. The pilot was fatally injured in the accident. Witness statements and evidence at the scene indicate the accident was caused by a pilot induced stall/spin.

Geary S. Monckton, IIC

Albuquerque FSDO SW-01