



Photo 2 - Closer view shows bent rotor blades and buckled skids