



**Photo 1 – engine showing 2 holes in crank case**



**Photo 2 – view of damage to crankcase**



**Photo 3 - #4 piston, connecting rod, and piston plug**