



Photo 1 – View from the front of the R-44 laying on its side



Photo 2 – View of the main rotor blades and top of the helicopter



Photo 3 – View of the helicopter from the rear



Photo 4 – View of the underside of the helicopter



Photo 5 – View of the top of the helicopter



Photo 6 – A mockup of the empennage and tail rotor gearbox and tail rotor blades



Photo 7 – View of the mockup of the tail rotor and empennage



Photo 8 – View of the tail boom where the tail rotor gearbox was attached



Photo 9 – View of tail rotor gearbox and one of the tail rotor blades



Photo 10 – View of the other tail rotor blade



Photo 11 – View of about a 6 ft section of the tail boom at the main wreckage site



Photo 12 – Photo of the top of the fuel cap



Photo 13 – View of the underside of the fuel cap



Photo 14 – View of the underside of the fuel cap



Photo 15 – Accident fuel cap installed on exemplar R-44



Photo 16 – View of exemplar R-44 tail rotor and empennage