



Photo 1 – Crankcase hole above the #1 cylinder



Photo 2 – Engine oil sump with visible debris



Photo 3 – Debris contents of the engine oil sump



Photo 4 - #1 Rod Connecting Rod Fragments - Photograph taken by Continental Motors