



Photo 1 – Oil Filter Adapter Assembly Component Layout



Photo 2 – Damaged Heli-Coil Insert Threads