



Photo 1 – Pre-accident photograph of N2440R on the ramp at Kickapoo Airport (KCWC), Wichita Falls, Texas.



Photo 2 - En route in VFR conditions (photo taken from passenger's personal cell phone).



Photo 3 - En route VFR above a solid overcast (photo taken from passenger's personal cell phone).



Photo 4 - Tree struck by N2440R.



Photo 5 - Left wing leading edge. Note indentation consistent with a tree strike and scattered branches next to left wing.



Photo 6 - Severed branch stump next to left wing.




Photo 7 - Front of airplane at the accident site.



Photo 8 - Left side of airplane. Note near-horizontal impact with mountainous terrain.



Photo 9 - Right side of airplane. Note heavily wooded area.



Photo 10 - Right wing and leading edge accordion-type crush damage.



Photo 11 - Propeller blade A. Note forward bending near the blade tip.



Photo 12 - Propeller blade B. Note spanwise striations on cambered surface.