




Photo 1 – Map of the area.



Photo 2 – View of a separated tail rotor blade on the ground near a hangar.



Photo 3 – View from ground witness marks looking to departure pad.



Photo 4 - View of witness marks on a separated tail rotor blade.



Photo 5 - View of witness marks on a separated tail rotor blade.



Photo 6 - View from the departure pad.



Photo 7 - View of the main accident site.



Photo 8 - View of the main accident site.



Photo 9 - View of the main accident site.



Photo 10 - View of the main accident site.




Photo 11 - View of the main wreckage and tail rotor guard.



Photo 12 - View of the main site and separated sections.



12BPhoto 13 - View of the tail rotor guard separation.



Photo 14 - View of the tail rotor guard separation.



Photo 15 - View of the cabin area of the main wreckage.



Photo 16 - View of a control tube separation.




Photo 17 - View of a hangar door with a witness mark.



17BPhoto 18 - View from a set of linear witness marks towards the impacted hangar door.



Photo 19 - View of both tail rotor blade separations.



Photo 20 - View of removed sparkplugs and injectors.