



Photo 1 – Wreckage site looking north



Photo 2 – Wreckage site looking east



Photo 3 – Wreckage site looking west



Photo 4 – Wreckage site looking south



Photo 5 – View of engine during examination




Photo 6 – View of engine accessory section



Photo 7 – View of propeller blades