



Photo 1 – Photo of front of the airplane at the accident site



Photo 2 – View of the initial point of contact



Photo 3 – View of initial point of contact with pieces of propeller blades



Photo 4 – View of damage to the left wing



Photo 5 – View of the damage to the left side of airplane



Photo 6 – View of damage to the right wing



Photo 7 – View of the empennage



Photo 8 – View of propeller and nose compartment



Photo 9 – View of splintered wooden propeller blade



Photo 10 – View of broken wooden propeller blade



Photo 11 – View of fuel selector



Photo 12 – View of inside of the main fuel tank



Photo 13 – View of the main fuel tank cork float



Photo 14 – View of the bottom spark plugs



Photo 15 – View of the aircraft weight and balance