



Photo 1 – View of the main wreckage.



Photo 2 - View of the main wreckage.



Photo 3 - View of the main wreckage.



Photo 4 - View of the main wreckage.



Photo 5 - Close up view of the main wreckage.



Photo 6 - View of the left engine.



Photo 7 - View of the left tip tank.




Photo 8 - View of a witness mark near the left tip tank.



Photo 9 - View of a witness mark consistent with the shape of the tip tank.



Photo 10 - View of the left propeller.



Photo 11 - View of separated airplane skin along a parkway.



Photo 12 - View of the right wing.



Photo 13 - View of the right engine within the main wreckage site.



Photo 14 - View of the recovered right propeller.



Photo 15 - View of a witness mark near the left propeller.



Photo 16 - View of a left wing spar.



Photo 17 - View of right wing control cables within the main wreckage.



Photo 18 - View of left wing control cables within the main wreckage.



Photo 19 - View of the right tip tank near the main wreckage.



Photo 20 - View of the left engine crankshaft.