



Photo 1 – View of the front of the inverted airplane at the accident site.



Photo 2 - View of the left side of the inverted airplane at the accident site.



Photo 3 - View of the aft side of the inverted airplane at the accident site.



Photo 4 - View of the right side of the inverted airplane at the accident site.



Photo 5 - View of the right side of the inverted airplane and debris path at the accident site.



Photo 6 - View of the right side of the inverted airplane and ground scar at the accident site.



Photo 7 - View of the right side of the inverted airplane and a separated propeller blade at the accident site.



Photo 8 - View of the drive chain and sprockets.



Photo 9 - View of the empennage.



Photo 10 - View of the fuselage.



Photo 11 - View of the propeller gearbox.



Photo 12 - View of the drive train layout.



Photo 13 - View of the right side wing trailing edge.



Photo 14 - View of the left side wing trailing edge.



Photo 15 - View of the right side main landing gear.



Photo 16 - View of the left side main landing gear.