



Photo 1 – Left side view of wreckage



Photo 2 – Front left side view of wreckage



Photo 3 – View of hangar that was struck



Photo 4 – View of engine during examination