

Number: SA15-04
Issued: July 15, 2015

SUBJECT: Release of Continental Motors Critical Service Bulletin CSB15-2 - Oil Cooler Cross Fitting Replacement

The following reference material is being provided to inform Cirrus customers of a recently released vendor service document. Contact the following vendor for additional information on the referenced service document and for service center locations.

Continental Motors, Inc.

Web: <http://www.continentalmotors.aero/>

Phone: 800-718-3411

1. DOCUMENT

Continental Motors Critical Service Bulletin CSB15-2 - Oil Cooler Cross Fitting Replacement.

http://www.continentalmotors.aero/Support_Materials/Publications/Service_Bulletin_Search/

2. EFFECTIVITY

SR22T Serials 0001 thru 1062, 1064, 1066, 1069 thru 1073

3. COMPLIANCE

Within the next 25 hours of engine operation or the next scheduled inspection or engine servicing, whichever occurs first.

4. DESCRIPTION

Continental Motors, Inc. (CMI) is aware of some occurrences in which there was a loss of engine oil due to a fractured nipple fitting that connects the cross fitting to the pipe bushing at the oil cooler. Design improvements consolidate the oil cooler cross fitting stack-up into a single part, which significantly increases the strength and provides a simplified installation procedure for installing the oil cooler cross fitting found on specified TSIO-550 and TSIOF-550 engines.

5. WARRANTY

Refer to Continental Motors Critical Service Bulletin CSB15-2 for warranty details.

Number: SA15-04R1

Issued: July 15, 2015

Revised: November 6, 2015

SUBJECT: Release of Continental Motors Critical Service Bulletin CSB15-2 - Oil Cooler Cross Fitting Replacement

The following reference material is being provided to inform Cirrus customers of a recently released vendor service document. Contact the following vendor for additional information on the referenced service document and for service center locations.

Continental Motors, Inc.

Web: <http://www.continentalmotors.aero/>

Phone: 800-718-3411

1. DOCUMENT

Continental Motors Critical Service Bulletin CSB15-2 - Oil Cooler Cross Fitting Replacement.

http://www.continentalmotors.aero/Support_Materials/Publications/Service_Bulletin_Search/

2. EFFECTIVITY

SR22T Serials 0001 thru 1062, 1064, 1066, 1069 thru 1073

3. COMPLIANCE

MANDATORY: Cirrus considers this service bulletin to be mandatory. Accomplish CSB15-2 at an authorized service center as soon as practicable. Compliance time begins upon receipt of the original issue of the service bulletin and is not to exceed 5 flight hours.

4. DESCRIPTION

Continental Motors, Inc. (CMI) is aware of some occurrences in which there was a loss of engine oil due to a fractured nipple fitting that connects the cross fitting to the pipe bushing at the oil cooler. Design improvements consolidate the oil cooler cross fitting stack-up into a single part, which significantly increases the strength and provides a simplified installation procedure for installing the oil cooler cross fitting found on specified TSIO-550 and TSIOF-550 engines.

5. WARRANTY

Refer to Continental Motors Critical Service Bulletin CSB15-2 for warranty details.

Number: SA15-04R2
Issued: July 15, 2015
Revised: November 11, 2015

SUBJECT: Release of Continental Motors Critical Service Bulletin CSB15-7 - TSIO-550-K Oil Cooler Cross Fitting Replacement

The following reference material is being provided to inform Cirrus customers of a recently released vendor service document. Contact the following vendor for additional information on the referenced service document and for service center locations.

Continental Motors, Inc.

Web: <http://www.continentalmotors.aero/>

Phone: 800-718-3411

1. DOCUMENT

Continental Motors Critical Service Bulletin CSB15-7 - TSIO-550-K Oil Cooler Cross Fitting Replacement.
http://www.continentalmotors.aero/Support_Materials/Publications/Service_Bulletin_Search/

2. EFFECTIVITY

SR22T Serials 0001 thru 1062, 1064, 1066, 1069 thru 1073

3. COMPLIANCE

MANDATORY: Cirrus considers this service bulletin to be mandatory. Accomplish CSB15-7 at an authorized service center immediately. Compliance time begins upon receipt of the latest revision of the service bulletin and is not to exceed 5 flight hours.

4. DESCRIPTION

Continental Motors, Inc. (CMI) is aware of some occurrences in which there was a loss of engine oil due to a fractured nipple fitting that connects the cross fitting to the pipe bushing at the oil cooler. Design improvements consolidate the oil cooler cross fitting stack-up into a single part, which significantly increases the strength and provides a simplified installation procedure for installing the oil cooler cross fitting found on specified TSIO-550-K engines.

5. WARRANTY

Refer to Continental Motors Critical Service Bulletin CSB15-7 for warranty details.