

AIRFRAME AND ENGINE EXAMINATION

CEN16LA033

A. EXAMINATION PARTICIPANTS:

Name : Jason Adame

Title: FAA Inspector

Baton Rouge, LA

B. SUMMARY

Examination of the recovered airplane wreckage was conducted on 10 November, 2015 at the facilities of Southern Air Transport. The inspector found that the engine's throttle arm was disconnected from the carburetor's throttle. The inspector also reported the castle nut had backed off, and the associated cotter pin was missing. He also noted that the carburetor had been replaced the day prior, to the accident flight.

C: Photos (courtesy the FAA)



Photo 1: Disconnected throttle arm

FAA photo



Photo 2: Nut

FAA photo