



Photo 1 – Accident airplane inverted in the field (provided by the FAA).



Photo 2 – Hole in the crankcase.



Photo 3 – Installed main crankshaft bearing.



Photo 4 – Installed thrust washers.



Photo 5 – Exemplar bearing and thrust washer assembly.