

Communication Summary

May 12, 2016

Information From: Mr. Robin Warstler, Pilot



Summary & Factual Information:

During a phone interview, Mr. Warstler indicated that there were no mechanical malfunctions of the airplane prior to the accident. The wind was reported about 140/9 and the wind was from his left. As the airplane got up to liftoff speed he felt the aircraft heading left. The airplane exited the runway and impacted ground obstacles. No injuries to Mr. Warstler, a safety pilot, and another passenger.

I can attest that the above summary is correct to the best of my knowledge:

Edward F. Malinowski
National Transportation Safety Board
Air Safety Investigator